

Visual Examination Report (VT)

Pyramid Co.

Client	<u>Acme Industries</u>	NDE Procedure No.	<u>318</u>	Rev.	<u>1</u>
Project	<u>147</u>	Exam- Date	<u>8/19/2009</u>	Time	<u>8:34:56 AM</u>
Project ID No.	<u>Job 754</u>	Project Client ID	<u>147</u>		
Location	<u>Building 1</u>	Project Lab No.	<u>34-A</u>		
Acceptance Standards	<u>ASME Section V</u>	NDE Specifications	<u>Simple Visual</u>		

Examination results


Piece ID	Area	Result	Discontinuity	Comments	Welder ID	Defect Length(s)	Welding Process
Sample 1	4	pass	none	none	34567	0	GMAW

Comments
none

Examination results

	<input checked="" type="checkbox"/> Direct Visual <input type="checkbox"/> Remote Visual <input type="checkbox"/> Translucent Visual
Lighting Equipment	Flashlight
Equipment/Devices used for technique	N/A

WELD LOCATION AND IDENTIFICATION SKETCH



Company
Pyramid Co.

Name
David W Craig

Level/Certificate #
Level 3 / Cert- 874

Signature (if required)
David W Craig

Date
8/19/2009